

## AccuForm Manufacturing Inc. Quality Assurance Clauses

All purchase orders are subject to the following referenced provisions as specifically noted on each individual purchase order or customer drawing.

### QC-1 AS9100 or ISO9001

The seller shall provide and maintain a system that complies with Specification ISO 9001 "Quality Management System - Requirements" or "AS9100 "Aerospace Standard." Notwithstanding the provisions of this clause, the seller is in no way relieved of the final responsibility to furnish the supplies or services specified.

### QC-2. INSPECTION REQUIREMENTS & NON-CONFORMING PRODUCT

The seller maintains an inspection system to ensure that all items furnished meet customer requirements. The seller is responsible for material acceptability and performance. Supplier shall notify AccuForm Manufacturing of any non-conforming process or product, and any major process changes. Q.A. may require corrective action for any products received that do not conform to all required specifications and/or referenced documents. Q.A. shall determine disposition of rejected items & advise purchasing, who shall undertake all required subsequent actions. If a Supplier Corrective Action Request (SCAR) is issued, the supplier must respond; or they will be unapproved for further procurements until the SCAR is satisfactorily resolved.

### QC-3. SOURCE SURVEILLANCE BY ACCUFORM MANUFACTURING INC. QUALITY REPRESENTATIVE

All items covered by this Purchase Order are subject to source surveillance by an AccuForm Manufacturing Quality Representative. This will include surveillance of the seller's procedures, and facilities. The seller shall furnish, at no cost to Buyer, necessary facilities and equipment, supply data, and perform tests as required by applicable drawings, specifications, and inspection instructions under surveillance of the AccuForm Manufacturing Quality Representative. Evidence of surveillance shall accompany each shipment.

### QC-4. SOURCE INSPECTION (PHYSICAL INSPECTION BY ACCUFORM MANUFACTURING INC.)

All items covered by this Purchase Order are subject to inspection at the seller's facility by an AccuForm Manufacturing Quality Representative prior to shipment. The seller shall furnish, at no cost, acceptable facilities and equipment to the AccuForm Manufacturing Representative for their inspection. The seller shall provide no less than forty-eight (48) hours advance notice to the Buyer to permit scheduling of source inspection. Evidence of source inspection shall accompany each shipment.

### QC-5. FIRST ARTICLES AND PRODUCTION TOOLING

The 1st Article produced under this order shall be submitted for AccuForm Manufacturing Inspection prior to making further shipments. This Inspection is solely for AccuForm Manufacturing convenience and shall not waive AccuForm Manufacturing right to reject any parts not conforming to this order. Acceptance of production tooling on this Purchase Order shall be contingent upon inspection and acceptance of the submitted 1st Article. Said 1st Article must conform to all design requirements, detail specifications and tolerance limits of Specification Control Drawings or similar documents submitted with and referenced within this Purchase Order. Supplier shall safely maintain all referenced records and documents for a minimum of two years or until advised by AccuForm Manufacturing to either return or discard them.

### QC-6. TEST MATERIAL

When test material is required as part of AccuForm Manufacturing obligation to fulfill their purchase order to the end user the supplier shall be required to apply 2 legible test piece results, unless otherwise instructed, to specified heats or production runs in accordance to AccuForm Manufacturing need. This shall be provided from AccuForm Manufacturing when shipping papers are requested.

### QC-7. CHEMICAL TEST REPORTS – SEE QC-6

### QC-8 PHYSICAL TEST REPORT – SEE QC-6

### QC-9. CHEMICAL AND/OR PHYSICAL TEST REPORTS – SEE QC-6

Each shipment, when required, must be accompanied by a legible and reproducible copy of all chemical and/or physical test reports identifiable with test parameters and products submitted. These reports must contain the signature and title of the authorized representative of the agency performing the test and must assure conformance to specification requirements.

### QC-10. ENVIRONMENTAL TEST REPORTS

Each shipment is accompanied by one (1) legible and reproducible copy of reports of actual test results identifiable with test parameters and products submitted. These reports contain the signature and title of the authorized representative of the agency performing the test and must conform to the specification.

### QC-11. STATEMENT OF CONFORMITY AND PROCESS CONTROL

Each shipment must be accompanied by a Certificate of Conformance referencing the P.O. & shipper number that ensures conformance to all referenced material and process specifications. Supplier must notify and obtain concurrence from AccuForm Manufacturing for any changes in either materials or processes specified on referenced Purchase Order.

### QC-12. FUNCTIONAL TEST REPORTS

Functional tests are defined as operational inspections, e.g. mechanical, electronic, hydraulic, etc. Each shipment shall include one legible and reproducible test report of actual results identifiable with test parameters and products submitted. These reports must contain the signature and title of the authorized representative of the agency performing the test and must assure conformance to specified requirements.

### QC-13. PROCESS CERTIFICATION

Each shipment must be accompanied by two (2) legible and reproducible copies of a certificate containing the signature and title of an authorized representative for all processes used. The certificate shall include the processing used, the specifications to which they conform, and the name of the agency that performed them if other than the seller. If parts are serialized, serial numbers must appear on the Process Certification. Outside Processor shall safely maintain all associated records and documents for a minimum of five years unless advised by AccuForm Manufacturing to either return or discard them.

### QC-14. NONDESTRUCTIVE TEST REPORTS

Each shipment must be accompanied by two (2) legible and reproducible copies of actual Nondestructive test results identifiable with acceptance requirements and material submitted. These reports must contain the signature and title of the authorized representative of the agency performing the inspection and must assure conformance to specified requirements.

### QC-15. CERTIFICATION OF X-RAY

All parts requiring testing certification will be submitted to AccuForm's approved X-Ray laboratory and processed in accordance with AccuForm Manufacturing and/or Government specifications and standards. X-ray findings will be reported on an appropriate form, including the name of the reader and the signature and title of an authorized laboratory representative. The X-Ray Films and two (2) legible and reproducible copies of the report must accompany the material. An adequate method of identifying and cross referencing each report and item must be provided. The report must record the grade to which it was reviewed, the severity level of discontinuity found, and the penetrometer gage used for readability of the radiograph of X-ray.

### QC-16. SOURCE INSPECTION - GOVERNMENT

Government inspection is required prior to shipment from your plant. When material is ready for inspection or, if practical, ten (10) days in advance thereof notify the government representative who normally services your plant. Upon receipt of this order, promptly notify the Government Representative so that inspection can be accomplished.

### QC-17. FINAL ACCEPTANCE

Final acceptance will be based on AccuForm Manufacturing inspection and testing results at destination.

### QC-18. MATERIAL TRACEABILITY

The supplier shall certify that material furnished is from the same heat, lot or batch, as applicable. Supplier identifies each item, package, or container of shelf life material with its cure or manufacture date, expiration date, and special storage and handling conditions in addition to the standard identification requirements. Where shipments contain parts with different cure dates, are from different heats, lots or batches, separation into sub-lot and separate certification of sub-lots is required. Two (2) copies of certification shall be included with each shipment for each lot or sublot.

### QC-19. ACCUFORM MANUFACTURING FURNISHED MATERIAL

The supplier shall certify that material used in fabrication is the material furnished by AccuForm Manufacturing and is not counterfeit.

### QC-20. INSPECTION AND/OR PRODUCTION TOOLING

Seller is held responsible for the protection, calibration and care other than normal wear of all Production and/or Inspection tooling furnished by AccuForm Manufacturing for use in the performance of purchase order requirements. All tooling shall be subject to AccuForm Manufacturing surveillance and/or inspection upon notice. Said tooling, or replacement tooling of equal quality, shall be returned in an acceptable condition upon demand or notice.

### QC-21. CALIBRATION

All items furnished under this P.O. shall be accompanied by certifications of calibration stating: All Standards used are traceable to the NIST (National Institute of Standards and Technology), ANSI-Z540 or ISO 10012-1 current revisions.

### QC-22. RIGHT OF ACCESS

Supplier shall grant right of entry and access by AccuForm Manufacturing, their customer and regulatory agencies to all facilities involved in this order and to all applicable records.

### QC-23. PART IDENTIFICATION REQUIREMENTS

Supplier ensures that all items are permanently and legibly identified. Identification requirements may include the following, as specified by purchasing or supplier documents, part number and revision level, manufacturer's identification, lot or date code, serial number, and quantity.

### QC-24. INSPECTION RECORDS

Documented evidence in the form of inspection records indicating actual results in accordance with drawings, specification and or purchase order requirements must be accompanied with each shipment.

### QC-25 RECORD RETENTION

All records must be maintained for a period of 7 years for purchase orders and 7-10 years for inspection data or contractual agreement.

### QC-26 SUPPLIER USING SECOND TIER SUPPLIER

Any supplier of services for AccuForm Manufacturing that may sub work to a second-tier supplier must obtain permission from AccuForm Manufacturing and flow down all applicable quality and record retention requirements to such supplier.

### QC-27 SUPPLIER NOTIFICATION OF CHANGE IN ADDRESS

All suppliers or vendors must notify AccuForm Manufacturing of changes in product and/or process, changes of suppliers, changes of manufacturing facility location and obtain AccuForm Manufacturing approval.

### QC-28 SUPPLIER SHIPMENTS

All suppliers shall be required to ensure that any product AccuForm Manufacturing instructs them to ship meets all customer and AccuForm Manufacturing requirements to include, PO, FOD, counterfeit and quality standard for cosmetic, dimensional and other specifications mentioned on the PO.

### QC-29 FAR/DFARS

AccuForm will assure Flow Down, as applicable, information to External Providers relevant to customer specified requirements.